

Defect Resolution Request

Defect ID	Title	Priority
DRR 015	Correction to MPD 15 for export sites	High

Defect			
Date raised	16/08/04	Contact name	John Casey – ESB MOIP
Date issued to MIG	19/08/04		

Part 1: Detail of Defect & Proposal

On the last page of MPD 15 there is a statement that MRSO will check and investigate when "Export occurs and there is no Generator associated with the meter point".

This bullet point should be removed and the following statement added:

‘An export site may validly have no Generator Unit ID associated depending on whether or not it is relevant for settlement. MRSO will carry out a manual periodic audit check on such sites to ensure correct records are maintained’

Impact of Defect on Market Processes

Incorrect representation of Market Process

Proposal

Proposal Type *(please tick one)*

New/modified working practice
 Amend market design
 No action
 Other

Description

Update MPD 15 to reflect updates above

Identification of Baseline Products Impacted

MPD 15 – Data Processing - QH Meter V 4.2

Part 2: IMPACT ASSESSMENT & DECISION:

Summary of Impact Assessment

Modifications Included

Reason for Modifications

DECISION

ACCEPTED	REJECTED	DEFERRED	COMMENT