

DR		1108		Update to description and usage of Delay Reason Code 'DE01' on 130D			Priority
Harmonisation Status		Progress to Change Request			CR Status	Approved	
					Status Date	12/12/2011	
Date	Version	Reason For Change				Version Status	
28/11/2011	v1.0	Initial version				Final	
PART 1 DETAIL OF DISCUSSION REQUEST/MARKET CHANGE REQUEST:							
Requesting Organisation(s)	NIE			Originating Jurisdiction	NI		
Contact name	Joan-Edel Smith						
Date Request Raised	28/11/2011			Originating Request			
Detail of Request							
Reason for Request							
<p>This discussion request proposes three changes</p> <ol style="list-style-type: none"> 1. That the description for Delay Reason code 'DE01' is changed from "Completion Certificate Required" to "Completion Certificate/Connection Card Required" 2. That 'DE01' will be used in NI 3. That 'DE01' will be sent on the 130D to notify Suppliers that a requested change of MCC will be delayed because a new Connection Card will be required from the customer before the work can be completed. <p>This situation will arise where an MCC which includes heating is being requested and the premise does not currently have an MCC which includes heat. NIE need to know the additional Heating Load that is required at the premise and the Connection Card will provide this information.</p> <p>This change will prevent the cost of an additional visit being charged to Suppliers unnecessarily. If NIE do not hold back the job until receipt of the Connection Card, then the electrician who makes the first visit will not be able to complete the job and will have to reschedule and wait for the Connection Card before returning to complete the job, thus incurring a re-visit fee.</p>							
Proposed Solution							
<p>NIE propose</p> <ol style="list-style-type: none"> 1. That the description for Delay Reason code 'DE01' is changed from "Completion Certificate Required" to "Completion Certificate/Connection Card Required" 2. That 'DE01' will be used in NI 3. That 'DE01' will be sent on the 130D to notify Suppliers that a requested change of MCC will be delayed because a new Connection Card will be required from the customer before the work can be completed <p>The code will be sent on the 130D in response to a 030 which is requesting a change of MCC from one that does not include heat to one that does include heat (N004/5/6/7).</p>							
Classification of Request							
Harmonisation Impacting		X		Harmonisation Baseline Version No.		TBD	
NI Specific		RoI Specific		Operational		Date of Transfer from HWG	
Scope of Request							
Design Documentation	Business Process	Market & MP Systems	Market Gateway (Hub)	MPCC/ EMMA	Schema	Web Forms	Extranet
X	X	X					

DR		1108		Update to description and usage of Delay Reason Code 'DE01' on 130D		Priority	
						Fast Track	
Harmonisation Baseline Documents impacted by Request							
Market Messages:	No impact						
Data Definitions:	No impact						
Data Codes:	Yes						
RoI MM Guide:	No impact						
NI MM Guide:	NI Market Message Implementation Guide - Meter Works						
Harm. Impact (RoI):	Yes						
Comment:							
Jurisdictional Market Design Baseline Documents impacted by Request							
Market Process Diagrams (MPDs):	TBD						
Guidance Documentation	TBD						
Briefing Documents:	TBD						
User and Technical Documents:	TBD						
Comment:							
PART 2 MARKET ASSURANCE:							
Applicability	DSO	Suppliers	TSO	SEMO	Generators		
	X	X					
Scope of Test	Business Solution Assessment	Integration Test Assessment	Data Transfer Testing	IPT	Other (specify)		
	X	X	X	X			
PART 3 RECOMMENDATION							
Recommended by		SIG		IGG	HWG		
ACCEPTANCE (Date)	REJECTION (Date)	NO RECOMMENDATION		COMMENT			
Reason for Recommendation							