

Defect Resolution Request

Defect ID	Title	Priority
DRR 0103	Removal of DG5A, DG6A and MCC68 (Autoproducer) and DG4 Unmetered DuoS Groups from Market Design	High

Defect			
Date raised	28/04/2006	Contact name	Tim Cragg – ESB Networks
Date issued to IGG			

Part 1: Detail of Defect & Proposal
<p>1) The following Duos Groups for Autoproducers are configured in the market design but are not being used and will not be required in the future:</p> <ul style="list-style-type: none"> • DG5A - LV Non-Domestic Non-MD Autoproducer NQH Sites only • DG6A - LV MD Autoproducer NQH Sites only • This means that these codes are still required in the Market Design to support Quarter Hourly sites but references to these DuoS Groups and NQH sites will need to be removed from the MCC Guidance Notes <p>2) It is intended to remove the association between Autoproducer sites and MCC10 and MCC68. The only MCC associated with Autoproducer sites should be MCC11. No Autoproducer sites are currently assigned to MCC10 or MCC68.</p> <p>3) In addition DG4 – Un-metered DuoS group is not being used at present and will not be required in the future because all un-metered sites are currently assigned to DG3 – Public Lighting.</p> <p>This means that the description currently applied to DG3 is misleading as this category currently contains all types of Un-metered sites and should be changed to DG3 – Un-metered.</p> <p>4) Lastly it is proposed to remove MCC68 QH Meter Configuration Code from all elements of the Market Design as no new sites are to be set up as this code and the two sites that we migrated across as this MCC at go-live have been re-assigned.</p> <p>Summary of Changes: Amend the Market Design so that the following 2 code values for DUoS Group are not associated with NQH Sites:</p> <ul style="list-style-type: none"> • DG5A - LV Non-Domestic Non-MD Autoproducer • DG6A - LV MD Autoproducer <p>Amend the Market Design so that Autoproducer sites are only associated with MCC11 and not MCC10 and MCC68.</p> <p>Remove references to the following DUoS Group as it is no longer needed in the Market Design</p> <ul style="list-style-type: none"> • DG4 – Un-metered <p>Amend the Code description of DG3 from Public Lighting to Un-Metered to reflect the types of site currently included in this category.</p> <p>Remove MCC68 as this is now a redundant code in the Market Design.</p> <p>Please Note: It is not intended to include this change in the June 2006 Schema release but it would be appropriate to include it in the following one.</p>

Defect Resolution Request

Part 1: Detail of Defect & Proposal			
Impact of Defect on Market Processes			
Minimal impact on processes as these codes are currently not used / redundant.			
Proposal			
Proposal Type (please tick one)			
New/modified working practice	<input type="checkbox"/>	Amend market design	<input checked="" type="checkbox"/>
		System Update	<input type="checkbox"/>
		Other	<input type="checkbox"/>
Description			
Identification of Baseline Products Impacted			
Market Design v5.1 (Data Codes)			
XML Schema v5.1			
MCC Guidance Notes v2.1			
DuoS, Transaction and PSO Payment Processes v1.1			
Part 2: IMPACT ASSESSMENT & DECISION:			
Summary of Impact Assessment			
Modifications Included			
Reason for Modifications			
DECISION			
ACCEPTED	REJECTED	DEFERRED	COMMENT